

HN-466 , 100 Re = 100000 Ma = 0.000 Ncrit = 11.000
 HN-466 , 100 Re = 200000 Ma = 0.000 Ncrit = 11.000
 HN-466 , 100 Re = 400000 Ma = 0.000 Ncrit = 11.000
 HN-466 , 100 Re = 600000 Ma = 0.000 Ncrit = 11.000
 AH69 , 59 Re = 100000 Ma = 0.000 Ncrit = 11.000
 AH69 , 59 Re = 400000 Ma = 0.000 Ncrit = 11.000
 AH69 , 59 Re = 600000 Ma = 0.000 Ncrit = 11.000
 AH69 , 59 Re = 200000 Ma = 0.000 Ncrit = 11.000

ust70

